Coordinate Metrology Society
Coordinate Metrology Systems Conference 2003
Greenville, South Carolina | July 21-25, 2003

CMS-2003-008

Objective Real World Uncertainty Analysis

AUTHORS
Tim Nielsen · Scott Sandwith

ORGANIZATION
The Boeing Company, Manufacturing Research and Development; New River Kinematics

Published by the Coordinate Metrology Society. Reference number CMS-2003-008.
Copyright remains with the author(s). Redistribution requires permission.

Objective Real World Uncertainty Analysis

By Tim Nielsen (Boeing's Manufacturing Research and Development)
Scott Sandwith (New River Kinematics)

The ISO (International Organization for Standardization) standards focusing on "Global Product Specification" require that part measurements be described by two numbers. The first is the result of the measurement and the second is the stated uncertainty. This uncertainty statement represents the estimated variability in the result.

Users often combine measurement systems by tying individual measurement systems together based on common reference points, and then assume they are still working within the instrument's published uncertainty. Alternatively, many users apply heuristics to determine the uncertainty as they progress along a chain of measurements. These methods provide very poor approximations of uncertainty in all but the most simplistic cases. Even in cases where only a single placement of an instrument is used, its measurements are typically tied in to a reference coordinate system. The uncertainty from this tie-in process is often ignored.



This paper addresses a number of practical metrology questions:

- What is the uncertainty of my instruments in the "real-world"?
- What is the effect of uncertainty propagation on the quality of my measurements?
- How can I make optimal use of my measurements to minimize uncertainty?
- Ok, it's nice to know the uncertainty of a point, but I'm fitting a sphere. What is the uncertainty of my fit?
- What about my hidden point bar?

The presentation provides answers to the questions

- Combine measurement systems to minimize your measurement uncertainty
- Characterize instrument uncertainty on the job. Extract component uncertainties from residuals. (Type A evaluation)
- Verify instrument performance before and after a job
- Determine point uncertainty fields
- How to take advantage of the relative uncertainty of the measurement components.
- Geometric fitting uncertainty (sphere, line, plane, cylinder, etc)

Timothy Nielsen	Scott Sandwith
_____	_____
	(206)575-1025
Boeing	New River Kinematics
P.O. Box 3707 5H-77 Seattle, WA 98124	Seattle, WA 98188